

Page 1 Of 2

Date Completed: _____ Failure Code: _____

Completed By : _____ Signature : _____

Accepted By : _____ Signature : _____

**** Delay Codes Legend ****

W=Whse C=CrSp T=Tag TL=Tool P=Plan
 ** Record Time Daily ** Delays

Emp No	Date	Hours	Code/Hrs
--------	------	-------	----------

This image shows a blank sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There are no margins, text, or other markings on the paper.

SCOPE:

1- THIS WO. IS TO BE USED AS A MEANS OF TRACKING THE LABOR COSTS FOR TEI TO GRIND AND FIT (48 ea) HORIZONTAL FUEL DIFFUSERS (HFDs) TO THE BURNER SUPPLY ELBOWS.

2- THE COST WILL BE BACK CHARGED TO
ADVANCED BURNER TECHNOLOGIES (ABT).

** IMPORTANT NOTICE **

YOU ARE RESPONSIBLE FOR YOUR OWN SAFETY AND MUST ENSURE THAT THE REQUIRED PPE IS WORN FOR EVERY JOB YOU ARE DOING. IF YOU HAVE ANY QUESTIONS CONCERNING THE WORK RULES, SAFETY CODES, OR REQUIRED PPE, PLEASE CONTACT YOUR SUPERVISOR.

Job Feedback/Historical Notes:



IP7_032331

CREW: 81

WORK ORDER TYPE: OTHER

03-96033-31

ISSUE DATE 01/06/11

Page 2 Of 2

** Work Order Parts List **

Part No	Description	PO/Req/SIR	Date Due	U/M	Reqd	Commit	Issued/Rcvd
1	DIRECT	04-45618-1	03/09/04	EA	1	0	1
2	DIRECT	04-45618-2	04/26/04	EA	1	0	1

IP7_032332